

Certified Craftsmen would like to introduce our Dryer Vent Cleaning Services.

We are certified by the Chimney Safety Institute of America-- or CSIA (see csia.org for more info)-- and as required for all contractors we are registered with Consumer Affairs (KVH# 13VH00984000).

Why is this important? Please continue reading:

As a property manager you are compelled to recommend an insured, well-trained, reputable contractor. How do you know if a contractor has any of these qualities? Looking for a certification such as one from the CSIA is a good place to start.

This means the certificate holder had to pass a test based on the NFPA 211 and NFPA 54 codebooks. In order to uphold their certified staus they must also maintain their certification through continued education.

We know the responsibility of a property manager to recommend a solid service company cannot be taken lightly. A service company that does not perform a thorough chimney or dryer vent cleaning or inspection can make an already hazardous situation worse.

Leaving a connector hose, vent or chimney damaged or unclean can create a real fire hazard for the homeowner and other residents. Unfortunately, we have seen this situation occur time and time again.

671-0131

CHIMNEY

Call Certified and rest easy.

(Community references available)

972-0200

MEMBER NATIONAL CHIMNEY SWEEP GUILD

visit us online: www.certifiedcraftsmen.com

Our Cleaning Process

This dryer (right) is in a typically tight location. It must be



moved to clean the combustible lint from under it and to clean and check the connector (left) for holes and/or deterioration, and to determine if the connector is of the proper type.

Note the lint on the floor and in the connector hose.

The bird guard (below) must then be removed.







With our **high-pressure blower** providing outward airflow to the dryer duct (left), we are now prepared to clean.



The vent is now clean and the combustibles have been removed from the duct and dryer area.*

*Although hard-piping is best as a type of connector, many times it is not practical.